



HUMIDITY TRANSMITTER

Model : TR-HUM1A4

Measure Range	10 %RH to 95 %RH
Output	4 - 20 mA 10 %RH = 5.6 mA 50 %RH = 12 mA 95 %RH = 19.2 mA
External Adjustment	ZERO VR SPAN VR
Power Supply	90 - 260 ACV 50 Hz/60 Hz
Operation Temperature	0 - 50 °C 32 - 122 °F
Operation Humidity	Less than 80 %RH
Accessory Included	Humidity probe
Optional Accessories	33% RH Humidity calibrator, RHA-33A 75% RH Humidity calibrator, RHA-75A
Mounting	Din rail or Wall
Case	ABS plastic
Others	Separate probe with plug

